

Annexure D

BUILDING SAFETY CERTIFICATE

No. _____

Dated: 26/05/2025

It is certified that the existing building TRIPTA PUBLIC SCHOOL..... (name of the building or premises) at CHALWARA, TEHSIL - JAWALI, DISTT. - KANGRA..... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	4				

The building is owned/occupied by Tripta Public School..... (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of H.P.P.W.D Jawali (Name of Department Govt.) on 26-5-2025 (date of inspection) in the presence of Principal, Rakesh Rang. (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26/5/2025 for a period of 2 yrs. (31/3/29) years in accordance with rule and subject to compliance of the specific conditions as appended.

1. No Earthquake resistant norms have been adopted for this building
2. No structural drawings have been approved by competent authority
3. The building has neither been designed nor constructed by H.P.P.W.D.
4. The building appears safe by visual inspection, hence fit for use

Issued on 26/5/2025 at Jawali by _____

[Signature]
Assistant Engineer
 Sub-Division
 H.P.P.W.D JAWALI

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature with Seal : _____
 Name : Tr. Ankit Kumar
 Designation : Assistant Engineer
 Name & Address of Department/ Office: H.P.P.W.D Sub Div. Jawali

Attested

[Signature]

Principal
Tripta Public School
Chalwara (Jawali) Kangra